

Company Name: 149 County Road Management Limited

Inspector Name: K. Zak

Inspection Date: 29 May 2025

Purpose

This site inspection record is used when undertaking regular site inspections and is solely for the purpose of recording and monitoring the common (communal) parts on behalf of the above company.

What Is Included

The below report comments on the general condition of the interior and exterior communal parts (where applicable) as they were found at the time of this inspection.



Please note: This inspection is carried out visually by the property manager or a competent person instructed by the property manager and should not be used for any other purpose than to comment and record the general state and condition of the common (communal) parts that are inspected during a routine site visit. Where further investigation, testing or remedial work is required, a competent person is instructed by the property manager.



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

| Internal Inspection | Acceptable | Not Acceptable | N/A | Comments | Action |
|--|------------|----------------|-----|---|--------|
| Entrances (Main doors) | ✓ | | | The entrance were secure at time of inspection. | None |
| Hallway (Communal Lobbies and Stairs) | ✓ | | | Hallway and stairs are clean and tidy. | None |
| Lighting (Standard and Emergency Lighting) | ✓ | | | The lights are working correctly, emergency lights have also been checked and are working perfectly. | None |
| Internal Doors (Compartment Doors) | | | ✓ | | None |
| Cupboard Doors (Electrical Cupboard Doors) | ✓ | | | Cupboard doors were secure at time of inspection. | None |
| Windows (Communal Windows) | ✓ | | | The communal windows appeared in good visual condition. | None |
| Signage (Communal Notices) | ✓ | | | The information board is displayed in a visible location and contains all the information regarding the building. | None |
| Additional Comments | | | | | None |



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

| External Inspection | Acceptable | Not Acceptable | N/A | Comments | Action |
|---|------------|----------------|-----|---|--------|
| Exterior Structure (The Building) | ✓ | | | The exterior structure of the building is in good condition with no visible issues. | None |
| Guttering (Gutters and Fascia) | ✓ | | | The guttering appeared to be in good visual condition. | None |
| Roofing (Tiles and Cladding) | ✓ | | | The roof was inspected from ground level and appeared to be in good visual condition. | None |
| Communal Grounds (Gardens and Common Areas) | ✓ | | | Communal grounds were tidy, well-kept, and free from litter. | None |
| Bin Store (Waste Disposal Areas) | ✓ | | | The bin area is clean and tidy. | None |
| Car Park (Vehicle Parking) | | | ✓ | | None |
| Bike Store (Bicycle Areas) | | | ✓ | | None |
| Additional Comments | | | | | None |

| Entrances (Main Doors) | Hallway (Communal Lobbies and Stairs) | Lighting (Standard and Emergency Lights) | Internal Doors (Compartment Doors) |
|--|--|--|------------------------------------|
|  |  |  | |
| Cupboard Doors (Electrical Cupboard Doors) | Windows (Communal Windows) | Signage (Communal Notices) | Additional Photos |
|  | |  | |

| Exterior Structure (The Building) | Guttering (Gutters and Fascia) | Roofing (Tiles and Cladding) | Communal Grounds (Gardens and Common Areas) |
|--|--|---|---|
|  |  |  | |
| Bin Store (Waste Disposal Area) | Car Park (Vehicle Parking) | Bike Store (Bicycle Areas) | Additional Photos |
|  | | | |